

How to install the cutting die of coin cell disc cutter AOT-CP60?




## Different dies for cutting electrode and battery separator:

## Battery electrode die




Battery separator die




Website: www.aotbattery.com Email: sales@aotbattery.com Tel: (+86)-592-7161550



Step1: Install upper die, and fasten it with screw.




Step2: Take off the rubber which is on the upper die.




Website: www.aotbattery.com Email: sales@aotbattery.com Tel: (+86)-592-7161550

Step 3: Match the upper die and lower die, make them closed in a good condition.




Step 4: Press the handle and hold on, make sure the holes are aligned.



Website: www.aotbattery.com Email: sales@aotbattery.com Tel: (+86)-592-7161550

Step 5: Fit and fasten the screws by the wrench, and then loosen the handle.



Step 6: Put on the rubber, then you can start cutting battery electrode



Website: www.aotbattery.com Email: sales@aotbattery.com Tel: (+86)-592-7161550